



## 由于E系列阵列上的Recovery Guru中报告了DONStore REV，驱动器DONStore无法识别

[https://kb-cn.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/INCOMPATIBLE\\_DOWNREV\\_DACSTO...](https://kb-cn.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/INCOMPATIBLE_DOWNREV_DACSTO...)

Updated: 周六, 12 7月 2025 13:58:32 GMT

### 适用场景

- NetApp E 系列
- NetApp SANtricity操作系统

### 问题描述

- 将新驱动器插入 存储阵列后、该驱动器显示为"不兼容"
- RecoveryGURU报告以下情况之一：
  - `INCOMPATIBLE_DOWNREV_DACSTORE-Recovery Failure Type Code: 205`

- INCOMPATIBLE\_UPREV\_DACSTORE-Recovery Failure Type Code: 204
- 存储阵列配置文件报告：
  - Drive at Tray XX, Slot XX  
Status: Incompatible  
Cause: Drive DACStore is unrecognizable.  
Mode: Incompatible