



断电后、无法通过共享端口访问H410S IPMI

https://kb-cn.netapp.com/on-prem/SolidFire/hardware_Kbs/Unable_to_access_H410S_IPMI_via_share...

Updated: Mon, 06 Oct 2025 01:01:17 GMT

适用场景

- NetApp H410S
- IPMI专用端口未连接以太网电缆
- 通常使用Bond1G 端口访问IPMI Web图形用户界面

注:建议不要使用IPMI共享端口、而不要使用IPMI专用端口进行持续使用。

问题描述

- 执行电源消耗后、IPMI Web图形用户界面未显示
- 对IPMI IP地址的ping响应不稳定

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'