



# NiCE

## 交换机错误地将IFGRP成员端口报告为L2环路

[https://kb-cn.netapp.com/on-prem/ontap/Ontap\\_OS/OS-KBs/Switch\\_reports\\_IFGRP\\_member\\_ports\\_as...](https://kb-cn.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Switch_reports_IFGRP_member_ports_as...)

Updated: Wed, 27 May 2026 17:01:15 GMT

### 适用场景

- ONTAP 9
- 网络连接
- IFGRP

### 问题描述

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

- 客户的数据交换机报告IFRP中的两个端口位于第2层环路中  
2025 Jan 22 04:36:41.639 NONJC6SA06B %FWM-2-STM\_LOOP\_DETECT: Loops detected in the network for mac 02a0.98e1.f45f among ports Eth1/13 and Eth1/14 vlan 142 -Disabling dynamic learn notifications for 180 seconds
- ONTAP IFRP配置正确、不会显示为问题描述的发生原因、因为ONTAP EMS中不会生成任何错误或警告日志。