



CONTAP-421967: QSFP28 P/N X65406 连接到 40/100GbE NIC 卡 P/N X1146A 时网络端口抖动

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-421967

Updated: 周五, 11 7月 2025 02:56:16 GMT

问题描述

安装在 40/100GbE NIC 卡 P/N X1146A NIC 中的 100G 单模 QSFP28 收发器 P/N X65406 (FINISAR 型号 FTLC1157RGPL) 出现抖动

vifmgr: vifmgr.portdown:notice]: A link down event was received on node node-02, port e2a.

vifmgr: vifmgr.portup:notice]: A link up event was received on node node-02, port e2a.

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'