



## 由于接管节点故障,A300 节点无法启动

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/A300\_node\_unable\_to\_boot\_due\_to\_faulty\_t...

Updated: Fri, 31 Oct 2025 19:00:34 GMT

## 适用于

- ONTAP 9
- AFF-A300
- BIOS 11.20

## 问题描述

• IPMI 故障后节点无法启动并停止到 LOADER

Failed to recover SP

IPMI:Get controller FRU inventory:failed

IPMI:Get midplane FRU 0 inventory:failed

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

Configuring Devices ...

IPMI PCI Slot Control failed.

BIOS POST Failure(s) detected: SP IPMI failure. Abort AUTOBOOT

LOADER>

• 更换主板无法解决此问题。