



HCI存储节点 Bond10G接口无响应、节点报告脱机

https://kb-cn.netapp.com/Legacy/NetApp_HCI/OS/HCI_Storage_Node__Bond10G_interface_Unrespon...

Updated: 周五, 11 7月 2025 08:19:23 GMT

适用场景

- NetApp Element软件
- NetApp H410S (H300S、H500S、H700S)
- NetApp H610S

问题描述

HCI存储节点绑定10G接口无响应、节点报告脱机