

NiCE

由于挡板故障，控制器前 LED 面板未点亮

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/Controller_Front_LED_panel_not_lit_due_to_…
Updated: Tue, 24 Nov 2026 04:55:12 GMT

适用于

- ONTAP 9
- AFF-A1K
- AFF-C30

问题

- 前面板 LED 板未点亮。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

- BMC 可能会正常报告 LED 状态。

  AFF-C30 输出示例：

  ```
  BMC filer-name*> system fru led show all
  FRU LED ID 11 = Bezel LED
  FRU LED ID 11 is on
  ```

© 2023 NetApp.No part of this document covered by copyright may be reproduced in any form or by any means—graphic, electronic, or mechanical, including photocopying, recording, taping, or storage in an electronic retrieval system—without prior written permission of the copyright owner. For more information, see Legal Notices.