



SolidFire H410S节点意外重新启动、并显示CPU致命错误-断言

https://kb-cn.netapp.com/on-prem/SolidFire/hardware_Kbs/SolidFire_H410S_node_reboots_unexpecte...

Updated: Mon, 06 Oct 2025 01:01:15 GMT

适用场景

- NetApp H410S
- NetApp Element软件12.5

问题描述

- Active IQ错误日志中显示节点脱机事件

```
709    2024-10-29T16:30:30.135Z    Error    node    XX    <Storage
Node>    0    Yes    2024-10-29T16:34:04.795Z    nodeOffline    The SolidFire
Application cannot communicate with Storage node having node ID xx.
```

- 登录到BMC并查看SEL日志以了解提供的详细信息

Select a health event log category:

Severity:

Keyword Search:

All Events

All Severities

Health Event Log: Max= 512, Used= 2 (event entries)

ACK	EID	Severity	Time Stamp	Sensor	Description
<input type="checkbox"/>	1	!	2024/10/23 13:06:55	Processor(OEM)	Configuration error@CPU12@DCU@TLB@Fatal error - Assertion
<input type="checkbox"/>	2	!	2024/10/23 13:06:55	Processor(OEM)	Configuration error@CPU12@DCU@TLB@Correctable error - Assertion

Page 1 of 1

64