



时区更改导致的 ONTAP 控制器中断

https://kb-cn.netapp.com/onprem/ontap/OS/ONTAP_controller_disruption_caused_by_time_zone_chan...

Updated: 周三, 17 4月 2024 21:21:58 GMT

状态信息

适用于

- ONTAP 9.7
- AFF 和 FAS 控制器

问题

在将存储系统的所有版本的 ONTAP 9.7 - ONTAP 9.7P8 过渡到标准时间时, IDT (以色列节省时间)和 NDT (纽芬兰夏令时)时区中的存储系统都会发生系统中断。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

PANIC: process on cpu15 hung (cron_admin) for 5007 milliseconds! in SK process cron_admin on release 9.7P7 (C) on Sun Oct 25 01:00:05 IDT 2020.