



CONTAP-449745: ONTAP 集群节点意外重新启动

https://kb-cn.netapp.com/on-prem/ontap/Ontap_OS/OS-Issues/CONTAP-449745

Updated: 周四, 10 7月 2025 15:08:17 GMT

问题描述

ONTAP集群节点意外重新启动:

protection fault on VA 0 code 0 cs:rip 0x20:0xffffffff803eedea in process NwkThd_00 on release 9.15.1P7 (C)

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'