



COETP-178487:以太网X522测试失败、但在硬件诊断中显示"通过"状态

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-178487

Updated: 周五, 11 7月 2025 21:08:23 GMT

问题描述

即使测试实际失败、硬件诊断中的以太网X322测试也会显示"通过"状态。

Ethernet X722 Test:

ethtool selftest test

Ethernet e0a ethtool selftest Test:

Test Start: 2023-12-25 05:08:31

test_cmd: ethtool -t e0a
The test result is FAIL
The test extra info:

Register test (offline) 0 Eeprom test (offline) 0

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

Interrupt test (offline) 0
Link test (on/offline) 1

PASSED

Ethernet e0a ethtool selftest Test Stop: 2023-12-25 05:08:32

此问题描述在以太网eOa的ethtool自检中标识。