



CONAP-211622:由于ONTAP证书不兼容、SSL升级预验证检查失败

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-211622

Updated: 周三, 09 7月 2025 01:46:35 GMT

问题描述

由于SSL证书不兼容、ONTAP升级预验证检查失败、因为ONTAP无法从基板管理控制器(BMC)获取传感器信息。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'