



CFNVRAM-4：由于 NV-DIMM 中检测到无法纠正的错误，导致 NVRAM 硬件发生故障

<https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFNVRAM-4>

Updated: 周五, 11 7月 2025 08:00:17 GMT

问题描述

- 节点因以下错误而关闭：

```
NVRAM in slot 6: uncorrectable memory error at address 0xeaea7fcf0 DIMM(1),  
Rank(0), Bank Group(3), Bank(0x2), Row(0xaea7), Col(0x3f6) in process idle:  
cpu12 on release 9.13.1P14 (C) on Sat Jun 21 17:28:24 JST 2025
```