



CN1610 集群交换机上的 UnsupportedSwitch_Alert

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/UnsupportedSwitch_Alert_on_CN1610_clust...

Updated: Fri, 17 Apr 2026 09:12:41 GMT

适用于

- NetApp ONTAP 9.13.1 及更高版本
- CN1610 集群交换机

问题

- 将 ONTAP 从 9.7 升级到 9.16 后，将显示以下警报：

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

```
::*> system health policy definition show -node <node name> -monitor ethernet-
switch -policy-id UnsupportedSwitch_Policy
    Node: <node name>
    Monitor: ethernet-switch
    Process Name: cshm
    Policy: UnsupportedSwitch_Policy
    Rule Expression: cluster_switch_support.model == "OTHER"&&
cluster_switch_support.show-model== "OTHER"&& cluster_switch_support.warning-
count2 > cluster_switch_threshold.entity-alert
    Variable Equivalence: -
    Policy Status: false
    Alert ID: UnsupportedSwitch_Alert
    Table and ID of Resource at Fault: cluster_switch_support.device
    Enable AutoSupport for This Alert: false
```