



更换 E-Series 货架中 IOM 后的固件版本不匹配

https://kb-cn.netapp.com/on-prem/E-series/Hardware-Kbs/Firmware_version_mismatch_after_replacing...

Updated: Thu, 16 Apr 2026 09:29:41 GMT

适用于

E-Series

问题

- 更换 E 系列货架中 IOM 后的固件版本不匹配

IOM status: **Firmware version mismatch**

Firmware Version: **0141 (Mismatched)**

Location: A
Product ID: DE212C
Part number: 111-04850+B1

IOM status: Failed
Firmware Version: 0100 (Mismatched)
Location: B
Product ID: DE212C
Part number: 111-04850+A3

- RECOVERY-GURU 报告 ESM_CODE_VERSION_MISMATCH-Recovery Failure Type Code: 31