



无法从ifgrp中删除前端交换端口后。错误：NbladeWriter PCP RPC错误 ioctlErr

https://kb-cn.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/After_headswap_port_cannot_be_remove...

Updated: 周五, 11 7月 2025 14:50:48 GMT

适用场景

- ONTAP 9
- FAS8700

问题描述

- 升级控制器或进行前端交换后、无法从特定节点上的接口组(ifgrp)中删除端口。

```
Cluster::*>ifgrp show -ifgrp a0a
Port Distribution Active
Node IfGrp Function MAC Address Ports Ports
```

```
-----  
Cluster-N1  
a0a sequential ff:ff:ff:ff:ff:ff none e0c  
Cluster-N2  
a0a sequential ff:ff:ff:ff:ff:fe full e1a, e1d  
Cluster-N3  
a0a sequential ff:ff:ff:ff:ff:fd full e1a, e1b  
Cluster-N4  
a0a sequential ff:ff:ff:ff:ff:fc full e1a, e1b  
4 entries were displayed.  
  
Cluster::~*>network port ifgrp remove-port -node Cluster-N1 -ifgrp a0a -port e0c  
Error: command failed: Failed to remove port from ifgrp. Nblade error:  
Unexpected error "NbladeWriter PCP RPC Error ioctlErr" encountered as a result  
of removing a port from the ifgrp.
```

- 尝试删除ifgrp会导致相同错误。