



无法从ifgrp中删除前端交换端口后。错误:NbladeWriter PCP RPC错误ioctlFrr

https://kb-cn.netapp.com/on-prem/ontap/Ontap\_OS/OS-KBs/After\_headswap\_port\_cannot\_be\_remove...

Updated: 周五, 11 7月 2025 16:11:21 GMT

## 适用场景

- ONTAP 9
- FAS8700

## 问题描述

• 升级控制器或进行前端交换后、无法从特定节点上的接口组(ifgrp)中删除端口。

Cluster::\*>ifgrp show -ifgrp a0a

Port Distribution Active

Node IfGrp Function MAC Address Ports Ports

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

------

Cluster-N1
a0a sequential ff:ff:ff:ff:ff:ff none e0c
Cluster-N2
a0a sequential ff:ff:ff:ff:ff:fe full e1a, e1d
Cluster-N3
a0a sequential ff:ff:ff:ff:ff:fd full e1a, e1b
Cluster-N4
a0a sequential ff:ff:ff:ff:ff:fc full e1a, e1b
4 entries were displayed.

Cluster::\*>network port ifgrp remove-port -node Cluster-N1 -ifgrp a0a -port e0c Error: command failed: Failed to remove port from ifgrp. Nblade error: Unexpected error "NbladeWriter PCP RPC Error ioctlErr" encountered as a result of removing a port from the ifgrp.

• 尝试删除ifgrp会导致相同错误。