



PANIC : 控制器插槽 X 中的 PCI 错误 NMI

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/PANIC_PCI_Error_NMI_in_slot_X_on_Contr...

Updated: Fri, 21 Nov 2025 07:56:55 GMT

适用于

AFF 和 FAS

问题描述

指向插槽 x 适配器卡的系统崩溃：

```
PANIC : PCI Error NMI from device(s):PLX PCIE 8724 switch on Controller,  
Qlogic FC 8G adapter in slot 3 on Controller, Qlogic FC 8G adapter in slot  
3 on Controller, Qlogic FC 8G adapter in slot 3 on Controller, Qlogic FC  
8G adapter in slot 3 on Controller.
```

```
PANIC : PCI Error NMI from
device(s):ErrSrcID(CorrSrc(0x5f20),UCorrSrc(0)), RPT(0,3,0):PLX PCIE 8764
switch in slot 6 on Controller, NETAPP NVRAM10 in slot 6 on Controller,
PLX PCIE 8764 switch in slot 6 on Controller, NETAPP NVRAM10 in slot 6 on
Controller

PANIC: PCI Error NMI from device(s):ErrSrcID(CorrSrc(0x200),UCorrSrc(0)),
RPT(0,2,0):PLX PCIE 8764 switch on Controller, QLogic FC/10GbE CNA in slot
1 on Controller

[node01: HSWL error: pcie.stealth.errors:debug]: params: {'pcie_errors':
'LVMR,1_0.PLX PCIE 8764 switch on Controller, PMC-Sierra SAS adapter in
slot X on controller. IIO1:RPT(128,3,0): Br[8764](172,4,0):
DevStatus(Corr), CorrErr(RpTim); Dv[8072](173,0,0) in slot X:
DevStatus(Corr), CorrErr(Rcvr,BTLP,BDLLP). '}
```