



在带有 ONTAP 的 Emulex HBA 上，状态为：0x87800000、状态为 1：0xa40c、状态为 2：0x0 的 SRAM DUMP

https://kb-cn.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/SRAM_DUMP_with_status_0x87800000_st...

Updated: 周六, 12 7月 2025 14:02:43 GMT

适用场景

- ONTAP 9.X
- Emulex主机总线适配器

问题描述

SRAM DUMP 是针对以下状态代码生成的：

示例：

```
[NETAPP01: fct_tpd_thread_0: scsitarget.hwpfct.errorReset:notice]: An error was encountered in the FC target driver on Fibre Channel target adapter 4b. The adapter will be automatically reset to clear the
```

```
status:0x87800000, status1:0xa40c, status2:0x0, DIP:1, RN:1, RDY:1, Dump  
owner:0 condition.
```