



IFGroup 端口在 ONTAP 升级后抖动

 $https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/IFGroup_ports_flapping_after_ONTAP_upgra...$

Updated: Fri, 31 Oct 2025 19:23:02 GMT

适用于

- ONTAP 9
- LACP
- IFGroups

问题描述

- ONTAP 升级后,IFGroup 中的所有端口不会保持在线:
- 在 EMS 中可以多次看到以下内容:
- [Node-01: vifmgr: vifmgr.portdown:notice]: A link down event was received on node Node-01, port e0a.

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

[Node-01: kernel: netif.linkUp:info]: Ethernet e0a: Link up.