



SPLinkDownAlert 频繁发生

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/SPLinkDownAlert_occurs_frequently

Updated: Sun, 19 Apr 2026 05:18:06 GMT

适用于

- AS2552
- FAS2554
- AFF8040
- AFF A300
- ONTAP 9
- 服务处理器 (SP)
- 基板管理控制器 (BMC)

问题

SPLinkDownAlert 频繁发生

```
9/8/2023 05:58:34 node-01 NOTICE hm.alert.cleared: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config cleared by monitor controlle
9/8/2023 06:00:35 node-02 NOTICE hm.alert.cleared: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config cleared by monitor controller
9/8/2023 06:18:34 node-01 ALERT hm.alert.raised: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config raised by monitor controller
9/8/2023 06:20:35 node-02 ALERT hm.alert.raised: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config raised by monitor controller
```