



[https://kb-cn.netapp.com/on-prem/ontap/Ontap OS/OS-KBs/Foreign LUN import fails on HP 3Par ...](https://kb-cn.netapp.com/on-prem/ontap/Ontap%20OS/OS-KBs/Foreign%20LUN%20import%20fails%20on%20HP%203Par...)

适用场景

- ONTAP 9.X
- HP 3PAR
- 外部 LUN 导入

问题描述

命令 `storage error show` 提供访问控制LUN已被识别、需要禁用

```
::*> storage errors show  
Disk: Switch_A:142.126L254  
UID:  
50002ACF:ccccB1AD:00000000:00000000:00000000:00000000:00000000:00000000:00000000:C
```

Switch_A:142.126L254 (50002acfccecb1ad): This array LUN is an access control LUN. It is not supported and should be masked off or disabled.