



## 电源维护期间集群交换机重启

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/Cluster\_switch\_reboot\_during\_power\_mainte...

Updated: 周二, 08 7月 2025 21:04:02 GMT

## 适用场景

- ONTAP 9
- Cisco集群交换机

## 问题描述

- 集群交换机重新启动
- 集群交换机发出断电警报

Jan 1 11:11:11 0.0.0.0-1 SIM[Cnfgr\_Thread\_]: sim\_util.c(4302) 11 %% ALRT Switch was reset due to power disruption or unexpected restart.(error[0x0]).

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'