



CFBMC-6970: BMC的公共网络接口上没有动态 IPv6 地址

https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-6970

Updated: 周五, 11 7月 2025 21:06:35 GMT

问题描述

BMC未在其公共网络接口上获取动态 IPv6 地址,导致无法通过 IPv6 访问,并可能影响支持 IPv6 的环境中远程管理。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'