



在硬件维护期间报告 EMS mgmtgwd.vreport.nodesUnreachable

https://kb-cn.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/EMS_mgmtgwd.vreport.nodesUnreachabl...

Updated: Fri, 31 Oct 2025 21:22:08 GMT

适用于

- ONTAP 9
- AFF-A700
- 同一集群中的某些节点正在进行硬件维护

问题描述

• EMS-LOG-FILE.GZ 报告 mgmtgwd.vreport.nodesUnreachable 错误:

[node01: mgwd: mgmtgwd.vreport.nodesUnreachable:error]: Vreport encountered some unreachable nodes. The report may be incomplete.

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

• MGWD.GZ 报告同一集群中的其他节点无法访问

示例: MGWD.GZ在 node01报告 node03无法访问,同时维护 node03

[kern_mgwd:info:3731] 0x82f58e300: 0: WARNING: tables::vreport: Skipping unreachable node: node03
[kern_mgwd:info:3731] 0x82f58e300: 0: WARNING: tables::vreport: Following Nodes were not reachable: node03
[kern_mgwd:info:3731] Warning: "Vreport" could NOT retrieve required information from the following nodes in the cluster node03.
[kern_mgwd:info:3731] Some discrepancies might not have been reported by "Vreport"