



EFOS升级后从集群LIF ping时持续丢包

https://kb-cn.netapp.com/on-prem/Switches/Broadcom-KBs/Continued_packet_loss_when_pinging_fro...

Updated: Sun, 05 Oct 2025 11:23:47 GMT

适用于

- 集群交换机 BES-53248
- AFF/FAS 交换配置

问题描述

- 在 BES-53248 集群交换机固件升级后，从所有集群 LIF 报告数据包丢失

```
[?] Tue Jun 17 23:49:29 +0100 [NODE-01: vifmgr:  
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging  
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-03_clus1  
(node NODE-03).
```

```
[?] Tue Jun 17 23:49:41 +0100 [NODE-01: vifmgr:
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-03_clus2
(node NODE-03).
```

```
[?] Wed Jun 18 00:33:36 +0100 [NODE-01: vifmgr:
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-04_clus1
(node NODE-04).
```

```
[?] Wed Jun 18 00:33:48 +0100 [NODE-01: vifmgr:
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-04_clus2
(node NODE-04).
```

```
[?] Wed Jun 18 00:34:24 +0100 [NODE-01: vifmgr:
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-02_clus1
(node NODE-02).
```

```
[?] Wed Jun 18 00:34:35 +0100 [NODE-01: vifmgr:
vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif NODE-01_clus2 (node NODE-01) to cluster lif NODE-02_clus2
(node NODE-02).
```

- 升级前没有 **CRC** 错误
- 升级后所有集群端口显示存在 **CRC** 错误
- 交换机或节点上的电缆或收发器没有报告问题
- 正在使用的交换机端口为 **49** 至 **52**