



eOM 端口和 BMC 无法 ping 通网关或在本地子网之外通信

 $https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/e0M_port_and_BMC_cannot_ping_gateway_\dots$

Updated: Fri, 31 Oct 2025 18:14:31 GMT

适用于

ONTAP 9

问题描述

- 一个节点上的 eOM 端口和 BMC 无法在本地子网之外建立任何连接。
- 通过 Laptop 直接连接到端口没有问题。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'