



NiCE

无法添加用于监控的交换机

https://kb-cn.netapp.com/on-prem/ontap/MC/MC-KBs/Failed_to_add_switch_for_monitoring

Updated: Wed, 27 May 2026 17:01:31 GMT

适用于

- MetroCluster FC
- ONTAP 9

问题

尝试添加交换机时出错：

```
Cluster_A::*> system switch fc add -address xx.xx.xx.xx -snmp-version SNMPv1 -snmp-community-or-
```

username netapp1 Error: command failed: Internal error. Failed to add switch for monitoring on node "Cluster_A-01" in cluster "Cluster_A". Reason: Failed to check if device located at "xx.xx.xx.xx" is from supported vendor. For further assistance, contact technical support.