



## 无法纠正的机器检查错误死机导致的 DMI 故障

[https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/Uncorrectable\\_Machine\\_Check\\_Error\\_panic...](https://kb-cn.netapp.com/on-prem/ontap/OHW/OHW-KBs/Uncorrectable_Machine_Check_Error_panic...)

Updated: Thu, 16 Apr 2026 22:58:31 GMT

### 适用于

- AFF A800 / AFF C800
- ONTAP 9

### 问题描述

在不可更正的机器检查错误期间，恐慌字符串指向多个设备。

```
PANIC : Uncorrectable Machine Check Error at CPUx. SKL_IIO Error:
STATUS<0xb38000000000e0b>(VALID,UC,EN,PCC,S,AR,CORR_ERR_STATUS(0),CORR_ERR_CNT(0)
Machine Check from device(s):Dv[2020](0,0,0): Link down, PCI Device 8086:2020
on Controller, PCI Device 8086:2025 on Controller, PCI Device 8086:a19c on
Controller, Seagate M.2 NVMe SSD on Controller, PCI Device 8086:2020 on
Controller, PCI Device 8086:2025 on Controller, PCI Device 8086:a19c on
Controller, Seagate M.2 NVMe SSD on Controller, PCI Device 8086:2020 on
Controller, PCI Device 8086:2025 on Controller, PCI Device 8086:a19c on
Controller, Seagate M.2 NVMe SSD on Controller, PCI Device 8086:2020 on
Controller, PCI Device 8086:2025 on Controller, PCI Device 8086:a19c on
Controller, Seagate M.2 NVMe SSD on Controller, PCI Device 8086:2020 on
Controller, PCI Device 8086:2025 on Controller, PCI Device 8086:a19c on
Controller, Seagate M.2 NVMe SSD on Controller, PCI Device 8086:2020 on
Controller, PCI Device 8086:2025 on Controlleversion: 9.10.1P1: Fri May 19
21:58:49 EDT 2023

conf : x86_64.optimize
```