



---

## ONTAP会发出警告、指出已违反根卷阈值、并触发警告

[https://kb-cn.netapp.com/on-prem/ontap/Ontap\\_OS/OS-KBs/ONTAP\\_warns\\_that\\_root\\_volume\\_thresho...](https://kb-cn.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/ONTAP_warns_that_root_volume_thresho...)

Updated: Fri, 17 Apr 2026 11:00:31 GMT

### 适用场景

ONTAP 9

### 问题描述

EMS警报：根卷低于警告阈值。